



Photo 1 – Front view of helicopter (Photo Provided by Flight Instructor)



Photo 2 – View of substantially damaged tailboom (Photo Provided by Flight Instructor)