

6/20/2023

N771ND

Statement

On May 28, 2023, I conducted flight training with a student pilot. The student was not a regular student of mine and was near completion of his private pilot certificate. We started the lesson with pattern work at GFK. We conducted the first landing and transitioned into a soft field takeoff. The students' control input and decision making seemed normal. The student started the takeoff and after rotation the aircraft deviated left of centerline. Student instantly applied right aileron instead of right rudder to counter "p" factor which resulted in the right wing dropping. I took the flight controls and told the student "my controls" recovered the takeoff and continued upwind with no issues. We continued the next pattern and landed without issue. Upon inspection I noticed a dent in the wingtip and right aileron. I reported these observations to maintenance.

Brenden Millett