

CEN23LA246

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side of Airplane (Courtesy of FAA)



Photograph 2 - Left Side of Airplane (Courtesy of FAA)



Photograph 3 - Oil Suction Screen Plug (Courtesy of Lycoming Engines)



Photograph 4 - Oil Suction Screen Plug and Screen Filter (Courtesy of Lycoming Engines)