

CEN23LA261


INVESTIGATION PHOTOGRAPHS




Photograph 1 - Airplane on the Trailer (Taken by NTSB)




Photograph 2 - Injection Oil Spray (Taken by NTSB)



Photograph 3 - Scoring on Piston (Taken by NTSB)



Photograph 4 - Scoring on Cylinder Wall (Taken by NTSB)



Photograph 5 - Newly Installed Oil Injection Line by Owner (Taken by NTSB)



Photograph 6 - Fragment of Old Oil Injection Line (Taken by NTSB)