



Shaun Williams
Senior Aviation Accident Investigator
Office of Aviation Safety - Central Region

Date: July 12, 2023
Subject: CEN23LA280, N828WP
Contact: Jason Walters, Pilot-in-Command

Mr. Walters stated that he was the pilot-in-command at the time of the accident. He said that he did not see the wires that he struck with the helicopter and the cables were too big for the wire cutters on the helicopter. He also stated that there were no mechanical failures or malfunctions that would have precluded normal operation.