



Photo 1 - Tail Rotor Blade Damage, Courtesy of FAA



Photo 2 - Tail Rotor Blade Damage, Courtesy of FAA