

John Brannen
Senior ASI
AS-CEN

Date: 7/27/2023
Subject: CEN23LA329
Contact: Peter Hupfer (FAA Inspector)

Mr. Hupfer responded to the accident scene shortly after the accident happened. He provided the following information:

- The airplane force landed in a corn field following a loss of engine power.
- Airplane nosed over in the tall corn.
- When he arrived on scene, he did not smell fuel smell and there was no evidence of a fuel spill on site.
- The airplane had damage to the vertical tail and rudder and also to the firewall.
- Leading edges of wings had dents from corn.
- Once flipped over, the tanks were checked. Did not appear compromised and only had a small amount of fuel in them, below a usable quantity.
- Airplane to be recovered to OSH where post-recovery exam will be done.