



Photo 1 – View of the right side of the helicopter after it landed at the airtanker base (courtesy of Brainerd Helicopter Service).



Photo 2 – View of the front of the helicopter after it landed at the airtanker base (courtesy of Brainerd Helicopter Service).



Photo 3 – View of the left side of the helicopter after it landed at the airtanker base (courtesy of Brainerd Helicopter Service).



Photo 4 – View of the rear of the helicopter after it landed at the airtanker base (courtesy of Brainerd Helicopter Service).



Photo 5 – View of tail rotor blade #1, showing the outward face (courtesy of Brainerd Helicopter Service).



Photo 6 – View of tail rotor blade #1, showing the inward face (courtesy of Brainerd Helicopter Service).



Photo 7 – View of tail rotor blade #2, showing the outward face (courtesy of Brainerd Helicopter Service).



Photo 8 – View of tail rotor blade #2, showing the inward face (courtesy of Brainerd Helicopter Service).



Photo 9 – View of the landing zone (courtesy of Brainerd Helicopter Service).



Photo 10 – View of the grass height at the landing zone (courtesy of Brainerd Helicopter Service).



Photo 11 – View of the damaged backpack (courtesy of Brainerd Helicopter Service).



Photo 12 – View of the damaged radio and the damaged tablet (courtesy of Brainerd Helicopter Service).