

N9663X Cessna 210B s/n 57963

STC installed SA02594SE
SkyView HDX with engine
monitor.

It appears that the fuel flow
transducer is installed between
the airframe fuel source and the
engine driven fuel pump.

Ezra R. Olson (FAA WICHITA)




Photo curtesy of Textron Air Safety ASI-23-CE-059

