

From: [REDACTED]
To: [REDACTED]
Subject: Re: CEN23LA399 (N9522Y, Beechcraft 35-33B) - Airframe Maintenance Records Question
Date: Saturday, March 30, 2024 11:01:05
Attachments: [image003.png](#)

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

I reviewed all of the maintenance records since engine overhaul and found nothing where an oil drain was purchased or installed. Let me know if you need anything else.

Marvin

[Sent from Yahoo Mail for iPad](#)

On Friday, March 29, 2024, 9:46 PM, Michael Hodges [REDACTED] wrote:

Thank you sir.

Mike

Mike J. Hodges, MS
Aviation Accident Investigator, Central Region
National Transportation Safety Board

14291 East 4th Avenue, Suite 7-300
Aurora, Colorado 80011

Cellular: [REDACTED]
Facsimile: [REDACTED]
Response Operations Center (24/7): 1-844-373-9922
Work Hours: Monday-Friday, 0900-1730 Central Time

"Don't let yesterday use up too much of today." – Will Rogers

From: Marvin McCanles [REDACTED]
Sent: Friday, March 29, 2024 8:38:48 PM
To: Michael Hodges [REDACTED]
Subject: Re: CEN23LA399 (N9522Y, Beechcraft 35-33B) - Airframe Maintenance Records Question

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

I will review the log tomorrow and let you know what I find. I'll send you a copy if there's an entry.

Marvin

[Sent from Yahoo Mail for iPad](#)

On Friday, March 29, 2024, 3:41 PM, Michael Hodges [REDACTED] wrote:

Hi sir,

I have a question please about N9522Y (Beechcraft 35-33B).

The engine had an Eaton Aeroquip E-Z oil drain sump valve (part number AE99950G) installed on it. Here is a photo of it:



I reviewed the maintenance records for the engine, and there was no entry of that valve being installed.

I spoke with America's Aircraft Engines in Tulsa, Oklahoma, who did the overhaul work on the engine, on April 28, 2003. They said it left their shop without a valve like that being installed.

Are you able to please check the airframe maintenance records to see if there are any entries about that valve being installed?

Thank you for the help.

Mike

Mike J. Hodges, MS
Aviation Accident Investigator, Central Region
National Transportation Safety Board

14291 East 4th Avenue, Suite 7-300
Aurora, Colorado 80011

Cellular: [REDACTED]

Facsimile: [REDACTED]

Website: www.nts.gov

Response Operations Center (24/7): 1-844-373-9922

Work Hours: Monday-Friday, 0900-1730 Central Time

"Don't let yesterday use up too much of today." – Will Rogers

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS

FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.