



Jason Aguilera
Senior Air Safety Investigator
Aviation Safety - Central Region

Date: November 17, 2023

Subject: CEN23LA411, N853HT

Contact: William Brown, FAA FSDO

FAA Inspector William Brown with the Kansas City Flight Standards District Office provided the following information concerning his fact gathering into CEN23LA411.

The pilot's family was not able to provide any aircraft or pilot records. The pilot did not appear to be a certificated Airman. The pilot flight experience could not be determined.

The airplane had been purchased by the pilot and partially disassembled for transport. The airplane was reassembled by an unknown person.

It is unknown if this was the airplane's first flight since being assembled.

---END---