

CEN23LA418

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial image of the accident site (Courtesy of Texas Emergency Management)

2531 Harwood Rd Gonzales TX

☉ 106°E (T) ☉ 29°31'31.62", -97°27'29.54" ±13ft ▲ 370ft



Gonzales County Crash
ER Paiz - TDEM DC17

N18994
24 Sep 2023, 08:28:07

Photograph 2 - Separated right wing (Courtesy of Texas Emergency Management)

2531 Harwood Rd Gonzales TX

☀ 108°E (T) ☉ 29°31'31.36", -97°27'28.71" ±13ft ▲ 365ft



Photograph 3 - Right side of airplane (Courtesy of Texas Emergency Management)

2531 Harwood Rd Gonzales TX

☉ 274°W (T) ☉ 29°31'31.23", -97°27'28.26" ±13ft ▲ 363ft



Photograph 4 - Left side of airplane (Courtesy of Texas Emergency Management)



Photograph 5 - Front of airplane and muffler (Courtesy of NTSB)



Photograph 6 - Muffler (Courtesy of NTSB)



Photograph 7 - Muffler endcap crack (Courtesy of NTSB)



Photograph 8 - Muffler (Courtesy of NTSB)



Photograph 9 - Tailpipe blockage (Courtesy of NTSB)



Photograph 10 - Inside muffler, flame tube lodged in tailpipe (Courtesy of NTSB)



Photograph 11 - Inside muffler, flame tube lodged in tailpipe (Courtesy of NTSB)



Photograph 12 - Flame tube lodged in tailpipe (Courtesy of NTSB)