

**From:** [REDACTED]  
**To:** [REDACTED]  
**Cc:** [REDACTED]  
**Subject:** Email report-CEN24FA049 (Annunciator panel)  
**Date:** Monday, March 25, 2024 14:52:09

---

Mike,

The annunciator panel from the accident aircraft was submitted to the Materials Laboratory for examination. The annunciator panel was radiographed to determine the filament status of the individual bulbs within the annunciator lights. Each individual annunciator light contained 4 bulbs. None of the bulbs exhibited hot coil stretching in any filaments.

If you have any questions, please let me know.

Nancy B McAtee  
Senior Chemist  
RE-30