



CEN24FA160 Hartsburg, MO G1000 Email Report

From Olivia Fowler <[REDACTED]>

Date Tue 11/19/2024 12:35 PM

To John Brannen <[REDACTED]>

Cc Christopher Babcock <[REDACTED]>

Email Report Instructions

The narrative from this email report may be used in other reports at the discretion of the IIC. This email should also be placed in the public docket by the IIC.

Email Report

The NTSB Vehicle Recorders Lab received the following components from the G1000 system that had been installed in N451MA:

- 1x GDU 1500 MFD: PN 011-01108-10, SN 43225499
- 2x GDU 1040 PFDs: PN 011-00972-10, SN 88956269, 88956241
- 1x GMC 710 Autopilot: PN 011-01020-10, SN 22005826

The GDU units have the option to record flight data to a secure digital (SD) card, however these units did not have SD cards installed and therefore no data was recorded.

The autopilot does not record flight data.

Prepared by: Olivia Fowler, Recorder Specialist, NTSB RE-40



Olivia Fowler (she/her/hers)

Mechanical Engineer - Recorder Specialist
Office of Research and Engineering

