

13 hr start slight lessons 10/11/19
~~engine problem loss of power~~

New Drive Belts 10/2022?

9/27/21 Loss of power in hover
8/2022 Replace fuel pump

1

10/9/18 install 162F tail rotor

7/2019 install new elastomeric bearings

4-5-2019 Engine drive belts new hoses
Belts; install electronic Ignition

7-1-2020 New tail rotor belts

11-17-2020 New Engine drive belts add
Idler for drive belts.

9-28-2021 New alternator and belt
New SS exhaust

8-15-2022 New fuel pump

10-23-2022 water pump kit

5-15-2023 New Cog drive and belt, idler
Rebuilt secondary drive

5-15-2023 New tail rotor belts #1 & 3

2-25-2024 " " " " #2

