

Date 4/24/2019

W/O# 17604



Airframe Logbook Entry AIRCRAFT: N 342ED

CRS AWKR298C

S/N 0485

25170 Aviation Ave., Davis, CA 95616

FlightTime 931.4 COMPLIED WITH CIRRUS AIRCRAFT SB2X-42-17, UPDATE PERSPECTIVE SYSTEM SOFTWARE FROM VERSION 0764.35 TO 0764.37. CONFIGURED SYSTEM FOR CUSTOMER'S AIRCRAFT WITH NO DISCREPANCIES NOTED.

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed.

Pertinent details of the repair are on file at this agency: Signed: [Redacted]

David Clarke AWKR298C



Date 9/1/2021

W/O# 19427

Airframe Logbook Entry

CRS AWKR298C

AIRCRAFT: N 342ED

S/N: 0485

25170 Aviation Ave., Davis, CA 95616

FLIGHT
METER

1277.7

REPLACED GARMIN GCU 478 RANGE KNOB WITH NEW. CLEANED OLD SEALANT FROM AFT GPS ANTENNA AND APPLIED NEW SEALANT. INSTALLED NEW GAP 26 HEATED AOA PROBE P/N 011-02964-60, S/N 34F800122. CONFIRMED CORRECT HEATER OPERATION.

TESTED TRIPLE ALTIMETER, ALTITUDE REPORTING SYSTEM, PITOT/STATIC SYSTEM, AND TRANSPONDER SYSTEM PER FAR 43, APPENDICES E AND F. THOSE SYSTEMS MET REQUIREMENTS OF FAR 91.411 AND 91.413 FOR NON-PRESSURIZED AIRCRAFT TO 25,000 FEET.

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed. Pertinent details of the repair are on file at this agency:

Signed: [Redacted]

Shawn Matthews AWKR298C

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hours	Min	Hours	Min	
Carried forward →					

Logbook Entry

DATE: 12/7/2021 ACFT: Cirrus SR22T REGISTRATION NO.: N342ED SERIAL NO: 0485

HOBBS: 1362.5 ACTT: 1362.5 ETT: 1362.5 EngSn:

WORK PERFORMED:

- Performed Engine oil change, Drained oil and examined filter no debris found. Replaced oil filter with AA48108-2 and safety wired, serviced engine with 8 qts of Phillips 20W50.

DATE: 12/8/2021

SIGN: [Redacted] AJP [Redacted]

5/28/2022 Cirrus SR22T N342ED SN: 0485

Hobbs: 1679.0 Flight: 1419.9

- Performed ENGINE oil and Filter change. Serviced with 8 qts Phillips 20w50, and Replaced oil Filter AA 48108-2. NO Debris noted in old filter. leak check Performed, NO leaks noted.

5/28/2022 [Redacted] AJP [Redacted]

9/25/2022 Cirrus SR22T Reg: N6JA. SN:0485 Hobbs: 1708.1 Flight: 1441.5

ENgSN:1007953 PropSN:NI675B

Performed Engine 100 hour/annual inspection referencing Far part 43 appendix D serviced with phillips XC 20W50 oil and filter part number AA48108-2. Compressions are as follows:
1:71/80 2:74/80 3:74/80 4:79/80 5: 75/80 6: 60/80

I certify this Engine has been inspected in accordance with annual inspection referencing FAR part 43 appendix D, and is determined to be in an airworthy condition and approved for return to service

9/25/2022 [Redacted] AJP [Redacted]