

Direct Action Aviation, LLC

Aircraft: TVAP-4, N42VZ
Aircraft TT: 63.6
Engine MN: IO-360-C1E6
TTE: 63.6
SOH: 63.6
Airframe S/N: 1080
Tach: 63.6
Prop MN: GA200L-70
TTP: 63.6
SPOH: 63.6
Date: 2/22/2023
Propeller S/N: No SN

- 1 C/W Conditional Inspection
- 2 Completed Engine oil change and Oil filter replacement.
- 3 Replaced RH Magneto
- 4 Adjusted & Checked Timing on both RH and LH Magnetos, No defects noted.
- 5 Serviced and inspected both Main and Nose wheel & Tires.
- 6 Inspected all Control Surface attachment points and linkages for freedom and movement and security of attachment.
- 7 Rotated tires to promote even tire wear.
- 8 Replaced LH Nav antenna.
- 9 Replaced Intercom.
- 10 Drained Fuel Tanks, Inspected & Cleaned all Fuel strainers for debris & contaminants. No Defects noted.
- 11 Revised Weight and balance of A/C.
- 12 CW 14 CFR 91.207 (d) Inspection of ELT.
- 13 Inspected Propeller for chips and signs of delamination.

Compression Test

Cyl 1 76/80 PSI
Cyl 2 76/80 PSI
Cyl 3 75/80 PSI
Cyl 4 77/80 PSI

This Conditional Inspection was Completed IAW the items listed in 14 CFR Appendix D to Part 43 and the Manufactures Service Manuals. This Aircraft is found to be in Airworthy Condition at this time and is approved for return to service per the work performed.

Ryan George A&P