

Carburetor Icing Probability Graph – CEN24LA096

Airplane: Lockwood AirCam, N1230R

Engine: Rotax 912 ULS (2)

Fuel: Automotive Gas (MOGAS) 91 octane ethanol free

Accident Date: 1/20/2024

Accident Location: Liberty Hill, Texas

Accident Time: 1320 CDT

Weather: METAR KGTU 201856Z 06007KT 10SM CLR
03/M12 A3049 RMK AO2 PRESFR SLP329 T00331122 \$

Celsius to Fahrenheit Conversion:

Temperature, 3° C = 37.4° F

Dew Point, -12° C = 10.4° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

