



Brian Rutt
Air Safety Investigator
AS-CEN

Date: March 6, 2024

Subject: CEN24LA119

Contact: Mark Baenen - Pilot

Mr. Baenen stated that he has no memory of the accident flight. He stated that he had recently changed carburetors on his engine, and this was his third flight with the new carburetor. He stated that previous flights with the new carburetor were uneventful, however he thought the fuel mixture was too rich. He stated that he intended to stay in the traffic pattern at Richland Airport on the accident flight.

///END OF STATEMENT///