



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: March 7, 2024
Subject: CEN24LA131 - Lubbock, Texas
Contact: Peter Keck - FAA Flight Standards

Inspector Keck stated that the airplane operator informed him the right wing outboard ribs were damaged during the accident and would need to be replaced.

----- end of summary -----