

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA143

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Remains of bird (Courtesy of pilot)



Photograph 2 - Bent pitch change link (Courtesy of pilot)



Photograph 3 - Bent swashplate drive link (Courtesy of pilot)