

N9996V IO-520-K1 S/N: 215903-R TSMOH: 488.1 Tach time: 2,130.2 11/14/23

DATE

Drained oil and serviced with 10 quarts of Aeroshell W-100. Installed new oil filter part number CH48108-2. Mace Moore, owner. PPL 3967079

LICENSE
NUMBER

N9996V IO-520-K1 S/N: 215903-R TSMOH: ^{532.0}~~3471.5~~ Tach time: ~~2,174.1~~ 4/1/2024
MLM 4/8/24

A.D. 2023-02-12 is not applicable, parts not installed. A.D. 2022-16-03 not applicable, parts not installed.

A.D. 2023-05-16 is not applicable, parts not installed. Complied with A.D. 2023-17-04 by installation of copper crush gaskets and removal of fiber gaskets. I certify that this engine has been inspected in accordance with a 100HR inspection and was determined airworthy at this time. Winston Larison,

AP

BROUGHT FORWARD

TOTALS