

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA196

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (courtesy of Piper pilot)



Photograph 2 - Stearman wing damage (Courtesy of FAA)



Photograph 3 - Piper wing damage (courtesy of FAA)