Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
4-12-24	1512 hrs	Ø	2184 hrs	Reinstalled prop after overhaul IAW propeller owners manual NO 139 section 3-6 & thrush service manual section 4-9. [redacted] Ap [redacted]
6-5-24	1512 hrs	Ø	2184 hrs	Reinstalled Prop IAW propeller owners manual no 139 section 3-6 & thrush Service Manual Section 4-9. [redacted] Ap [redacted]

1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** **FAA Form 8130–3, AIRWORTHINESS APPROVAL TAG**	127638
4. Organization Name and Address: MAXWELL AIRCRAFT SERVICE, INC. 5800 CRYSTAL AIRPORT ROAD MINNEAPOLIS, MN 55429		5. Work Order/Contract/Invoice Number: 127638

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	HARTZELL PROPELLER	HC-B3MN-5L/LM11693N	1	BUA33587	OVERHAULED

12. Remarks:

BLADE SERIAL NOS: L67669, L67673, L67674
OVERHAULED PROPELLER IN ACCORDANCE WITH HARTZELL PROPELLER MANUALS 118F REVISION 35, 133C REVISION 45, 159 REVISION 87, AND 202A REVISION 65.
COMPLIED WITH HARTZELL SERVICE BULLETINS 136 REVISION I, 280, 374 REVISION 1, AND 404 REVISION 2.
COMPLIED WITH HARTZELL SERVICE LETTERS 61Y REVISION 15, 167, 188, 217, 258 REVISION 1, 351, 364, 366, AND 367 REVISION 1.
COMPLIED WITH HARTZELL SERVICE INSTRUCTION 169.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

14a. ☑ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature: [redacted]	14c. Approval/Certificate No.: [redacted]
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): CONRAD E. MAXWELL [redacted]	14e. Date (dd/mmm/yyyy): DECEMBER 19, 2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

MAXWELL AIRCRAFT SERVICE

5800 Crystal Airport Road
Minneapolis, MN 55429

[redacted]

Certified Repair Station No. UF2R211L

Repair Order No. 127638

Date: 12/19/2023

Propeller Logbook Entry

Propeller Model No. HC-B3MN-5L/LM11693N **Serial No.** BUA33587 **N Number:** N529KC **PTT:** UNK **TSOH:** 0.0

Blade Serial Nos. L67669, L67673, L67674

Overhauled propeller in accordance with Hartzell Propeller Manuals 118F Rev. 35, 133C Rev. 45, 159 Rev. 87, and 202A Rev. 65. Complied with Hartzell Service Bulletins 136 Rev. I, 280, 374 Rev.1, and 404 Rev. 2. Complied with Service Letters 61Y Rev. 15, 167, 188, 217, 258 Rev. 1, 351, 364, 366, and 367 Rev. 1. Complied with Hartzell Service Instruction 169.

Inspector:

[redacted]

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
04-07-2021	Hobbs: 1211	TSN: 539 hrs		inspected prop IAW Periodic inspections pg 5-7 - pg 5-10
Cleaned blades & serviced with aeroshell No. 5 grease IAW maxwell prop stop and Lubrication procedures				
pg 6-7 — [redacted] — AP [redacted]				
5-11-22	738.6	738.6	1410.6	inspected prop IAW Periodic inspections pg. 5-7 - Pg 5-10 Cleaned
blades & Serviced with aeroshel NO. 5 grease IAW maxwell prop stop and Lubrication Procedures				
pg 6-7 ADs Complied with dated 5-11-22 — [redacted] — AP [redacted]				
5-15-22	1118 hrs	1118 hrs	1790.8	inspected prop IAW Periodic inspections pg 5-7 — pg 5-10 Cleaned blades
& serviced with aeroshell NO.5 grease IAW Lubrication procedures pg. 6-7 AD's complied with thru 5-15-23.				
[redacted] [redacted] AP				

[redacted]

5800 Crystal Airport Road

Certified Repair Station No. UF2R211L

MAXWELL

Repair Order No. 127638

N529KC **PTT:** UNK **TSOH:** 0.0

Inspector:

1. Approving Civil Aviation Authority/Country:	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130–3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 127638
FAA/United States		
4. Organization Name and Address:		5. Work Order/Contract/Invoice Number: 127638

5-1-17	Hobbs 756	TSN - 84 Hrs		Cleaned Blades Serviced Hubs with No 6 Aeroshell grease [redacted] dp
5-10-18	Hobbs [redacted]	TSN - [redacted]		Cleaned Blades Serviced with Aeroshell No 6 grease [redacted] dp
5-1-19	Hobbs 918.1	TSN - 246.1 Hrs		inspected prop IAW Periodic inspections pg 5-7- pg. 5-10. Cleaned blades and Serviced with aeroshell NO. 6 grease IAW Lubrication Procedures Pg 6-7. [redacted] dp
5-31-20	Hobbs: 1086.7	TSN: 414.7 hrs		inspected Prop IAW Periodic inspections pg. 5-7-pg 5-10. Cleaned blades and serviced with aeroshell NO. 6 grease IAW Lubrication Procedures Pg. 6-7. [redacted] dp