

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA259

INVESTIGATION PHOTOGRAPHS



**Photo 1 - Helicopter at accident site, left
(Courtesy of Pilot)**



**Photo 2 - Helicopter at accident site, aft left
(Courtesy of Pilot)**



**Photo 3 - Helicopter at accident site, aft right
(Courtesy of Pilot)**



**Photo 4 - Helicopter at accident site, right
(Courtesy of Pilot)**



**Photo 5 - Aft fuselage, tailboom, horizontal stabilizer, vertical fins, and tail rotor.
(Courtesy of Pilot)**



**Photo 6 - Tailboom damage
(Courtesy of Pilot)**



**Photo 7 - Tailboom, horizontal stabilizer, vertical fins, and tail rotor.
(Courtesy of Pilot; Edited by NTSB)**



**Photo 8 - Remnants of the agricultural load hose
(Courtesy of Pilot; Edited by NTSB)**



**Photo 9 - Remnants of the agricultural load hose
(Courtesy of Pilot; Edited by NTSB)**