



Jason Aguilera
Senior Air Safety Investigator
Aviation Safety - Central Region

Date: August 26, 2024

Subject: CEN24LA264

Contact: Timothy Grigsby, FAA Aviation Safety Inspector

FAA Aviation Safety Inspector Timothy Grigsby examined the airplane and witnessed a gear swing inspection on the airplane following the accident. He found that the gear warning horn was intermittent, but would sound properly if the switch was lightly tapped. No other anomalies were detected during the landing gear swings.

---END---