



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: January 2, 2025
Subject: CEN24LA268 - Arcola, Texas
Contact: Insp. Phillip Powell, FAA Flight Standards

Inspector Powell reported that both mechanics involved in the annual inspection acknowledged that they did not install safety wire on the gascolator after the annual inspection.

----- *end of summary* -----