



Alexander Lemishko
Senior Air Safety Investigator
NTSB, Central Region

Date: July 20, 2024

Subject: Memorandum for the Record CEN24LA281
FAA Examination Findings

Contacts: Alexander Lemishko - NTSB IIC
William Brown – FAA IIC Kansas City FSDO

The FAA examined the airplane at Mansfield Municipal Airport and reported:

Flight control continuity was established from the cockpit to all flight control surfaces. All interruptions were due to impact forces. The engine had drive continuity. Throttle connections from the cockpit to the engine were intact.

Alexander Lemishko

Senior Air Safety Investigator
NTSB, Denver, Colorado