



Cory Maxon
Air Safety Investigator
Aviation Safety – Central Region

Date: September 3, 2024
Subject: CEN24LA322, Phone Interview
Contact: Travis Turner – Pilot

Mr. Turner, the pilot of N3613W, stated that on the day of the accident he had successfully completed two landings. On the third landing of the accident flight, the airplane landed hard, bounced, and he attempted to recover by flaring the nose up as a wind gust pushed the airplane to the left of runway centerline. Mr. Turner stated that on the landing he hit his head on the glareshield and momentarily lost consciousness. When he regained consciousness, the airplane was flying towards and impacted the trees to the east of runway 17.