

ENGINE No. 2
MAKE: Hawker
MODEL: 900XP
S/N: HA-0015
REG. NO: N526FC
WORK ORDER: HK6355



Date: January 18, 2024
ACTT: 8130.4 **ACTL:** 4490
ENGTT: 7954.9 **CYC:** 4400
Make: Honeywell
Model: TFE731-50R
S/N: P-122135

Complied with the Following Scheduled Inspections:

- 1) Complied with 150 -250 Hour routine inspection on No. 2 engine IAW the Honeywell LMM 72-03-06 CH 72-00-00.

I certify that the above work was performed IAW Hawker 900XP Aircraft Maintenance Manuel Rev. A17 and/or approved FAA Data and was determined to be in airworthy condition with respect to the work performed under this work order.

Chris Gaston, Hawker Lead for West Star Aviation, CRS 3WTR399B.

The above work was performed IAW Hawker 900XP Aircraft Maintenance Manuel Rev. A17 and/or other FAA Approved Data. I certify that in accordance with FAR 91.409(f)(3) Inspection Program that this Aircraft is determined to be in Airworthy Condition with respect to the work performed. Pertinent details on file at this Repair Station under noted work order.

Joseph M. McNutt, Inspector for West Star Aviation, CRS 3WTR399B.