



Laura Abraham
Air Safety Investigator
Central Region

Date: 8/31/2024

Subject: CEN24LA335 - telephone conversation

Contact: Kenneth Reick

Mr. Reick reported that while departing from runway 15 at Lawrence Regional Airport (LWC), Lawrence, Kansas, the airplane drifted left. He put in right rudder pedal to correct. However, the airplane continued left and veered into the grass.

---end summary---