

National Transportation Safety Board

Office of Aviation Safety

Washington, DC 20594



September 12, 2024

Clayton J. Brackett



Dear Mr. Brackett:

The NTSB Regional Office in Denver, Colorado was notified on August 31, 2024, regarding an airplane accident involving N9020X in Coopersville, MI. Due to the airplane receiving substantial damage during the accident it is requested that you complete the enclosed Pilot/Operator Aircraft Accident Report NTSB 6120-1 form. Please complete the applicable areas in pages 3 through 11 of the report, to the best of your ability, and sign at the bottom of page 11. An additional copy is enclosed for your use. Please keep this copy and return the other to Andrew Finne via the enclosed UPS Return Label, email at [REDACTED] or fax at [REDACTED]

Under the Independent Safety Board Act of 1974, as amended, 49 U.S.C. 1132(b), the National Transportation Safety Board (NTSB) is charged with developing and enforcing rules concerning the notification and reporting of aircraft accidents. The NTSB's rules, codified in the Code of Federal Regulations, Title 49, Part 830, require that you file a report on NTSB Form 6120.1/2 within 10 days of the accident.

If you have any questions please call me at [REDACTED]

Sincerely,

Andrew Finne
Air Safety Investigator
AS-CEN

Proof of Delivery

Dear Customer,

This notice serves as proof of delivery for the shipment listed below.

Tracking Number

[REDACTED]

Weight

0.40 LBS

Service

UPS Next Day Air®

Shipped / Billed On

09/12/2024

Additional Information

Signature Required

Delivered On

09/13/2024 11:02 A.M.

Delivered To

[REDACTED]

Received By

BRACKET

[REDACTED]

Left At

Residential

Reference Number(s)

CEN24LA336

Please print for your records as photo and details are only available for a limited time.

Sincerely,

UPS

Tracking results provided by UPS: 09/13/2024 2:39 P.M. EST