



John Brannen
Senior Air Safety Investigator
AS-CEN

Date: October 10, 2024

Subject: CEN24LA339

Contact: Steven White (FAA Inspector)

Spoke with Steven White, FAA Inspector assigned to the accident involving N40939. He said he responded to the scene and the airplane was heavily damaged. There was damage to the inboard right wing, but the fuel tank wasn't compromised. The left wing had outboard damage, but its tank was also not compromised. There weren't any leaks evident, and no visible fuel was in either fuel tank.