



Michael J. Hodges
Investigator-In-Charge
Office of Aviation Safety, Central Regional Office

Date: 09/11/2025

Subject: CEN24LA342 - N4081S (Piper Aircraft, PA-28R-200) Engine Mount Information

Greg Thurston, aviation safety inspector, from the Federal Aviation Administration Minneapolis Flight Standards District Office, confirmed with Aerospace Welding Minneapolis (located in Eagan, Minnesota), that the engine mount that was on N4081S (Piper Aircraft, PA-28R-200) at the time of the accident is part number is 67119-57. Aerospace Welding Minneapolis reported that the engine mount does not have a serial number on it.

Sean Holloway, air safety investigator, from Piper Aircraft, confirmed that the engine mounts for this airplane are not serialized.

Nothing Follows