

CEN24LA348

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Airplane on the runway (Courtesy of operator)



Photograph 2 - Abrasion damage to the lower fuselage (Courtesy of Federal Aviation Administration)