

CEN24LA358


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Historical photograph of the helicopter, showing the right side (courtesy of the operator)



Photograph 2 - Historical photograph of the helicopter, showing the left side (courtesy of the operator)



Photograph 3 - View of the substantial damage on the bottom of the main rotor blade (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the substantial damage on the top of the main rotor blade (courtesy of the Federal Aviation Administration)