



Mitchell Gallo
Senior Aerospace Engineer
Aviation Safety - Central Region

Date: December 23, 2024

Subject: CEN24LA366, Brake System Examination

Contact: AMF Aviation

AMF Aviation stated the left side fluid was low but still had pressure. No pressure or fluid on the right side due to the wheel assembly being torn off in the accident. The brake pads look to be in newer condition with plenty of material. No obvious problems were identified with the brake systems.