

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA374

RECORD OF CONVERSATION

Harold V. Robertson, FAA Principal Avionics Inspector

October 14, 2024

Interviewee: Harold V. Robertson, FAA Principal Avionics Inspector
Date/Time: October 14, 2024 / 0930 CDT
Location: Telephone Call
Investigator(s): Andrew Todd Fox, NTSB Air Safety Investigator

NTSB Investigator Fox explained that the purpose of the phone call was to establish if Mr. Thomas M. Leonard provided FAA Inspector Robertson with his total flight experience and his total flight time in the accident airplane make/model (Cub Crafters CCX-2000).

FAA Inspector Robertson stated that Mr. Leonard reported having a total flight experience of 1,727.6 hours, of which 1,558.1 hours were flown as pilot-in-command. Additionally, Mr. Leonard reported having flown 29.6 hours in tailwheel-equipped airplanes, of which 15.1 hours were flown in the accident airplane (Cub Crafters CCX-2000; N822TL).