

CEN24LA381

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Horizontal Stabilator (Source: Current Airplane Owner).



Photograph 2 - Damaged Empennage (Source: Current Airplane Owner).