



U.S. Department of Transportation
Federal Aviation Administration
Washington, DC

Master Minimum Equipment List (MMEL)

Revision: 6
Date: 11/23/2018

AIRBUS HELICOPTERS EC130 B4, EC130 T2 (TCDS H9EU)

Steven R. Weaver, Chair
Flight Operations Evaluation Board (FOEB)

Federal Aviation Administration (FAA)
Fort Worth-Aircraft Evaluation Group (FTW-AEG)

[REDACTED]
Fort Worth, Texas 76177

Telephone: [REDACTED]

Fax: [REDACTED]

REVISION NO. 6
DATE: 11/23/2018

PAGE NO. XV

AIRCRAFT:
EC130 B4, EC130 T2

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
3320-03 "FASTEN SEAT BELTS/ NO SMOKING" Light (Cockpit)	(O) Procedure for crew to ensure the FASTEN SEAT BELTS and NO SMOKING sign in the cabin is operative, or a procedure is used to notify passengers when the seat belts must be fastened and smoking is not allowed.
3340-04 Auxiliary Landing Lights (STC SR09587RC)	(M) Procedure for maintenance to ensure system is deactivated and secured.
3340-05 Controllable Search Light (STC SR09587RC)	(M) Procedure for maintenance to ensure system is deactivated and secured.
3444-01 Radio Altimeter System	(O) Procedure for crew to ensure alternate procedures are established and used, night operations is not performed with NVGs; no night off-airport landings or landings at un-improved areas; for flight at night, the pilot must evaluate terrain and obstacles along the route and fly at such an altitude so as to ensure all terrain and obstacles along the route of flight are cleared vertically by no less than 500 feet; flight at night is not conducted over water or terrain without surface lights, and pilot is aware of potential degraded AP performance on ILS GS or LPV vertical. (M) Procedure for maintenance to ensure repairs are made within 10 flight days and system is deactivated, secured and placarded.