

Date/Tach	Tail Rotor Maintenance Record	T/Rotor TSMO	T/Rotor TT/HR	Aircraft TT/HR
4/25/08	Changed Allthread adjusting Bolts on Carry Over Tail rotor slide all new nuts Bolts & washers added new Support To Vertical stabilizer.			
8/15/09	New Tail Rotor Blades. Bend in tip of old set. Replaced with 6953A & 6953B. Installed Chaper Tail Rotor slider @ same time.	170.0	170.0	170.0
8/21/10	Replaced Tail Rotor Pulley Bearings	208	208	208
9/14/24	Inspected tail rotor pulleys, bearings, bolts, bolt tension All checked good. Greased tail rotor slider.	231.2	231.2	231.2
N 314 AC	Page No. 2	Total Time		