

CEN25LA035

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident Site (Courtesy of Federal Aviation Administration)




Photograph 2 - Accident Site (Courtesy of Federal Aviation Administration)



Photograph 3 - Fuel Selector Position at Accident Site (Courtesy of Federal Aviation Administration)



Photograph 4 - Number 2 Cylinder Assembly (Courtesy of Federal Aviation Administration)



Photograph 5 - Number 4 Cylinder Assembly and Throttle Cable Linkage (Courtesy of Federal Aviation Administration)



Photograph 6 - Hobbs Meter (Courtesy of Federal Aviation Administration)