





-18
3 5/8
-19

Nº 11 DRILL THRU.



-20 BEARING CAGE ASSY.
FULL SIZE




-28 PLATE (2)

NOTE:
CUT 1/16 SLOT IN - 6
FOR WELD FLOW O.
- 68 BUSHING

STICK ASSEMBLY
Q'D. FULL SIZE

-22 RUDDER CABLE ASSEMBLY
TWO REQ'D. FULL SIZE



18-3-M
SLEEVE - NICO PRESS

AN 115-21
SHACKLE

AN 100-4
THIMBLE - 2 PL'S.

CABLE - CONTROL
1/8 DIA. x 7 x 19
x 123 LSH.
(MIL-W-1511-A)

1/4 DRILL
8-PL'S. AS SHOWN

OP 40
Drill #40