



Brian Rutt
Air Safety Investigator
AS-CEN

Date: January 11, 2025
Subject: CEN25LA059
Contact: Phillip Powell - FAA Inspector

Inspector Powell visually inspected the electrical system of N5450L which included the alternator, voltage regulator, battery, drive belt, and all associated wiring. The inspector found no anomalies that would have precluded normal operation. ///END OF STATEMENT///