

Brian Rutt
Air Safety Investigator
AS - CEN

MEMORANDUM OF RECORD

Date: 10/30/2025

Subject: CEN25LA059 - Cockpit Video Summary

Video recorded from inside the AA-5's cockpit revealed the AA-5's engine was operating normally during the approach and landing. It did not show any evidence of the pilot of the AA-5 attempting to either increase spacing between his airplane and the 182T or conduct a go-around.