



Aaron Sauer
Sr. Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 12/30/2024

Subject: CEN25LA065

Contact: FAA Inspector Wood

FAA SAT FSDO Inspector Wood reported that he examined the airplane where it came to rest during the accident. Inspector Wood noted no visible fuel in the fuel tanks, and neither tank had been compromised. The carburetor bowl and a filter line contained some residual fuel, and gascolator contained no fuel.