



CEN25LA077


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of FAA)



Photograph 2 - Fuel Flow Transducer Attachment Fittings



Photograph 3 - Fuel Flow Transducer Attachment Fittings



Photograph 4 - Debris Found in Fuel Injector Nozzle/Engine Cylinder No. 1



Photograph 5 - Partially Blocked Diaphragm Metering Stem



Photograph 6 - Extracted Debris From Diaphragm Metering Stem



Photograph 7 - Debris From Diaphragm Metering Stem