


CEN25LA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Tailboom (Courtesy of Repair Facility)