



The pilot refused to provide a signed NTSB Form 6120 for completion of this accident.