



SOUTH ST. PAUL, MN LOCATION

AIRCRAFT SERVICES

PHONE: [REDACTED]

FAX: [REDACTED]

WO# 81172

Written By [REDACTED]

DEPT. 31



CUSTOMER INFORMATION

NAME	AgSun Avionics	#
ADDRESS		
ADDRESS		
CITY, STATE		

AIRCRAFT INFORMATION

MAKE	Air Tractor	
MODEL	AT 802A	T.T. 17.9
REG. NO.	N4025K	
SER. NO.	802A-1187	

DATES

	ACTUAL
ARRIVAL	4/28/25
COMPLETION	4/29/25
DEPARTURE	4/29/25

SERVICE DESCRIPTION

Removed Air Tractor GCU P/N# 61737-1 S/N# 81101511 and installed a servicable Air Tractor GCU P/N# 61737-1 S/N# 80291208. Performed all ops check of GCU with a run-up and verified GCU output was within limits per Air Tractor Owner's Manual Maintenance page, 2-47. GCU output was 27.7 volts.

The aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this agency under this work order number.

Preliminary Inspection

Hidden Damage Inspection

Progressive Inspection

Final Inspection

LOGBOOKS MADE AVAILABLE

UNSAT	SAT
☒	☐
☐	☐
☐	☐
☐	☐

YES ☐ NO ☒

Signed [REDACTED]

CRS# RJWR 380K

Date

FOR WIPARE, INC.
4/29/25